



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: September 29, 2006

Supervisor DDH

Mine Name: L-1 (Leisigange)
Operator Name: Color Country Rock
Preston Hafen
115 South Main
Veyo, Utah 84782

Permit number: S/053/068
Date: September 13, 2006
Time: 3:00 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Inactive

Weather: Clear, getting hot

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated	Comment	Enforcement
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspected the site while in the area.

Directions to Site:

See previous inspection report.

Inspection Summary:

The site remains the same as in appeared during my last inspection. The road into the site is still washed out just below the site. The fire that went through the area last spring impacted this mine site.

Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspector's Signature

Doug Jensen

Date:

9/29/06

dj:pb

cc:

Color Country Rock
Russ Shreiner, BLM, St George FO

O:\M053-Washington\S0530068-Leisigange\inspection\09142006insp.doc